



# LV Relay Racks

## Horizontal position of mounting rails and support angle brackets




## Vertical position of support angle brackets



The support angle brackets RASA12BK3 need to be put at U2, U5, U11, U17, U23. At U2, they support a fan tray; at all other positions, they support the LV power supplies.

*view from back of relay rack*

## Vertical position of strain relief bars




The strain relief bars HCM190UBK1 are mounted at the rear vertical mounting rails. They need to be put one hole underneath U4, U10, U16, U22. See drawing.

# HV Relay Racks

---

## Horizontal position of mounting rails and support angle brackets



## Vertical position of support angle brackets

The support angle brackets RASA22BK3 need to be put at U1 to support the HV main frame. See picture on page 1.

## Vertical position of strain relief bars

To be determined.