

### **DCS issues**

These are few issues which shifters have been complaining about. The source of these issues are nova ECL entries:

1. During the process to put APDs from a Cooling stage to a Warm stage, clicking "Configure warm APDs" in the CSS monitor doesn't seem to work.
2. FD APD temperature monitor CSS window sometimes fails to respond.
3. Power Supply summary GUI for ND sometimes appear disconnected.
4. Sometimes the APDs/FEBS are staying in alarmed state.