

## VME BPM - Milestone #16570

### Improvements for auto-tune operation

05/17/2017 10:30 AM - John Diamond

<b>Status:</b>	New	<b>Start date:</b>	05/17/2017
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
Requested improvements in order to operate SY BPMs with Auto Tune.			
<b>Subtasks:</b>			
Bug # 16571: Flat positions being reported intermittently			<b>New</b>
Task # 16572: Put together a test stand			<b>New</b>
Task # 16573: Establish alarms for SBPMxx nodes			<b>New</b>
Task # 16574: ACNET support for beam threshold			<b>New</b>
Task # 16575: Error state during spill			<b>New</b>
Task # 16576: Investigate reading back attenuator settings from transition crate			<b>New</b>
Task # 16577: Improve error handling of CAN bus communication			<b>New</b>