

VME BPM - Bug #16571

Milestone # 16570 (New): Improvements for auto-tune operation

Flat positions being reported intermittently

05/17/2017 10:35 AM - John Diamond

Status:	New	Start date:	05/17/2017
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
See e-log entry: https://www-bd.fnal.gov/Elog/?orEntryId=106774			
In this plot Adam expected that VP100 (red) should show the same roll-off as VP94. After rebooting the crate the roll-off appeared on VP100.			

History

#1 - 05/17/2017 10:36 AM - John Diamond

This is intermittent. Adam will notify us if he notices the problem occurring again.

In the mean-time we should investigate on the test stand.