

## VME Intensity Monitor - Support #20732

### Update firmware on all MI/RR Toroids

09/04/2018 11:31 AM - Elliott McCrory

<b>Status:</b>	Closed	<b>Start date:</b>	09/04/2018
<b>Priority:</b>	Normal	<b>Due date:</b>	09/21/2018
<b>Assignee:</b>	Elliott McCrory	<b>% Done:</b>	100%
<b>Category:</b>	Deploy & Config	<b>Estimated time:</b>	18.00 hours
<b>Target version:</b>		<b>Spent time:</b>	12.00 hours

#### Description

MI 40 is already up to date, so this is the model for the rest of the systems.

Aisha suggests that we do MI 30 first and MI 10 last.

Node	Location	Current Version	Updated	Comments
m40tor	MI 40	0abd05		Already at the latest version
mi30tor	MI 30	0abb02		
m52tor	MI 50			cannot ping 9/4/18
n60tor	MI 60 N			cannot ping 9/4/18
s60tor	MI 60 S	0abc02		
m10tor	MI 10	0bbb0a		Cannot figure out firmware version, 9/4/18

#### History

##### #1 - 09/04/2018 11:32 AM - Elliott McCrory

Figuring out the scope of work

##### #2 - 10/01/2018 11:35 AM - Elliott McCrory

- % Done changed from 0 to 80

##### #3 - 10/17/2018 12:22 PM - Elliott McCrory

- Status changed from New to Closed

- % Done changed from 80 to 100