

PIP-II IT HWR - Feature #24622

Freq / Detune Error Button and Pressure Transducer Readback to be added to LV.

07/12/2020 01:10 PM - Shrividhyaa Sankar Raman

| | | | |
|---|--------------------------|------------------------|-------------|
| Status: | Resolved | Start date: | 07/12/2020 |
| Priority: | Normal | Due date: | |
| Assignee: | Shrividhyaa Sankar Raman | % Done: | 100% |
| Category: | | Estimated time: | 0.00 hour |
| Target version: | | Spent time: | 21.00 hours |
| Description | | | |
| <ul style="list-style-type: none">• Freq / Detune Error Button - FPGA Write address required.• Pressure Transducer Readback to be added. | | | |

History

#1 - 07/13/2020 08:08 AM - Shrividhyaa Sankar Raman

- % Done changed from 0 to 40

- Assignee set to Shrividhyaa Sankar Raman

- New button has been added.
- Pressure Transducer Readback has also been added.
- These features are yet to be tested.

#2 - 07/22/2020 11:55 AM - Shrividhyaa Sankar Raman

- % Done changed from 40 to 100

Please refer to bug#24646 for issues wrt the readback.

#3 - 07/22/2020 11:56 AM - Shrividhyaa Sankar Raman

- Status changed from New to Resolved

#4 - 08/09/2020 10:24 AM - Brian Chase

Pressure transducer readback does not work. Do we know where the problem is?