

## Recycler Injecton Closure Application (PA4187, R52) - Bug #8037

### Booster > MI line trim calibration file needs to be updated

03/09/2015 07:46 AM - Kyle Hazelwood

<b>Status:</b>	New	<b>Start date:</b>	03/09/2015
<b>Priority:</b>	Normal	<b>Due date:</b>	
<b>Assignee:</b>		<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	0.00 hour
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
The trim calibration files for I52 and R52 for the Booster > MI line do not match. I52 appears to be believable while R52 is junk.			