

PIP II IT SSR1 - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
25181	Bug	Resolved	Low	Feedback gain ranges	Philip Varghese	01/27/2021 11:53 AM
25180	Bug	Resolved	Normal	Beam Loading Compensation timing values are off by a factor of 5	Shrividhyaa Sankar Raman	01/25/2021 11:58 AM
25179	Bug	Resolved	Normal	SSR1 Freq Track Error	Shrividhyaa Sankar Raman	01/25/2021 12:13 PM
25178	Bug	New	Normal	Labview FFT	Shrividhyaa Sankar Raman	11/07/2020 11:48 AM
25019	Bug	New	High	Cavity signal on SSR1-8 has fast spikes.	Philip Varghese	09/25/2020 04:22 AM
24894	Bug	Closed	Normal	When LV is turned off, code also stops running.		10/05/2020 08:50 AM
24738	Bug	Resolved	Normal	Pulsed mode operation of SSR1	Shrividhyaa Sankar Raman	01/27/2021 11:44 AM