## drvgen - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 20371 | Bug | Assigned | Normal | TSI-148 bridge does not support a master window with multiple data transfer modes | John Diamond | 07/23/2018 11:07 AM |
| 20408 | Bug | Resolved | Normal | runtime_error in generated getDeviceInSlot() does not include the driver name | John Diamond | 07/23/2018 11:27 AM |
| 20402 | Bug | Resolved | Normal | Constants generated for bitfields and enums can cause redeclaration | John Diamond | 07/23/2018 10:30 AM |
| 20432 | Bug | Work in progress | Normal | Kernel-level xxxmod_device_get() routine has bbpm250x12 hard-coded | John Diamond | 07/24/2018 03:00 PM |