llrf-hwr-2cavity-firmware - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
24921	Feature	Resolved	Normal	Beam Loading Compensation and DAQ modes	Philip Varghese	01/25/2021 12:00 PM
24771	Feature	New	Normal	Detune block error signal		08/12/2020 08:59 PM