llrf-hwr-2cavity-firmware

	2021-3				2021-4					2021-5				2021-6				2021-7					2021-8			
	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
PIP-II IT HWR		**PIP-II IT HWR**																								
llrf-hwr-2cavity-firmware																										
Resonance control goes with the wrong (...)		**Work in progress**																								
Resonance controller needs diagnostics		**Work in progress**																								
ADC alignment on start up		**New**																								
Detune block error signal		**New**																								
Beam Loading Compensation and DAQ modes (...)		**Resolved**																								