uBoone Operations - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
9653	Feature	New	Normal	Install more powerful fan pack from PMT HV crate		07/16/2015 03:45 PM
9082	Feature	New	Normal	Improvements to Alarm Area Panel and Alarm Tree for improved status visibility		06/09/2015 03:41 PM
9036	Bug	New	Normal	update the /home/uboonedaq/ directory on glomation-sbc-4	Sowjanya Gollapinni	06/04/2015 12:01 AM
9023	Bug	New	High	investigate high Wiener internal temperatures in PL508 (CrateRails) supplies	Sowjanya Gollapinni	06/03/2015 11:47 AM
9002	Necessary Maintenance	New	Normal	Submit EDR, get appoval		06/02/2015 05:43 AM
8864	Support	New	Normal	Slow Control Monitoring	Sowjanya Gollapinni	05/18/2015 02:08 PM
8862	Support	Accepted	Normal	Laser Monitoring	Matthias Luethi	05/19/2015 10:14 AM
8861	Support	Resolved	Normal	HV Monitoring	Sarah Lockwitz	10/09/2015 07:08 AM
8860	Support	Resolved	Normal	DAQ Monitoring	Wesley Ketchum	10/09/2015 07:09 AM
8859	Support	New	Normal	Cryogenics Monitoring	Ben Carls	05/18/2015 01:54 PM
8858	Support	New	Normal	Calibration Monitoring	Ben Carls	05/18/2015 01:52 PM
8857	Support	New	Normal	Beam Monitoring	Tia Miceli	05/18/2015 01:51 PM
8841	Necessary Maintenance	New	Normal	GUI laser	Thomas Strauss	05/18/2015 09:58 AM
8840	Necessary Maintenance	New	High	Grating platform	Matthew Toups	05/18/2015 09:48 AM
8839	Necessary Maintenance	New	Normal	Assign permanent port numbers to the rs232 connection	Matthias Luethi	05/18/2015 09:58 AM
8834	Idea	New	Normal	KeyBox at LArTf or control room for the UV laser	Matthew Toups	05/18/2015 06:34 AM
8833	Necessary Maintenance	Accepted	Normal	Check eth port is the connectivity to readout works	Thomas Strauss	05/23/2015 10:04 AM
8832	Necessary Maintenance	Accepted	High	mount home directory from ubdaq-prod cluster to uv laser 1	Wesley Ketchum	05/23/2015 10:00 AM
8831	Necessary Maintenance	New	Normal	Exercise full readout test with UV laser (all seb's) to confirm functionality of laser 1 & 2	Wesley Ketchum	05/18/2015 06:27 AM
8830	Necessary Maintenance	Accepted	Normal	Write Laser Power on procedure after power outage	Thomas Strauss	05/23/2015 10:03 AM
8827	Necessary Maintenance	Assigned	Normal	Setup UV Laser Trigger Connection to DAQ	Matthias Luethi	05/18/2015 06:27 AM
8802	Necessary Maintenance	New	High	Investigate separation of test stand NIM logic and beam timing NIM logic in DAQ room	Georgia Karagiorgi	05/14/2015 02:43 PM
8801	Necessary Maintenance	New	High	Investigate the use of anti-static mats on the platform		05/14/2015 02:37 PM
8800	Necessary Maintenance	New	High	Investigate and eliminate source of zig zag noise in the detector	Tia Miceli	05/14/2015 03:22 PM
8799	Necessary Maintenance	New	Normal	Understand operations of liquid level probes	Tia Miceli	05/14/2015 03:22 PM
8767	Necessary Maintenance	New	Normal	Relabel uboonedaq-seb-02		05/12/2015 05:44 PM
8766	Necessary Maintenance	Resolved	High	Review beam trigger logic at LArTF	Georgia Karagiorgi	10/09/2015 07:06 AM
8764	Necessary Maintenance	New	Normal	Determine detailed samples to be taken with muon counter system	Matthew Bass	05/12/2015 03:45 PM
8763	Necessary Maintenance	Resolved	High	Determine how PMT system will be read out in conjunction with muon telescope	Taritree Wongjirad	10/09/2015 07:07 AM
8762	Necessary Maintenance	New	Normal	Populate PMT system NIM bin with appropriate modules	Taritree Wongjirad	05/12/2015 03:42 PM
8761	Necessary Maintenance	Resolved	High	Develop slow monitoring of drift HV current and voltage read back	Sowjanya Gollapinni	10/09/2015 07:08 AM

#	Tracker	Status	Priority	Subject	Assignee	Updated
8759	Necessary Maintenance	New	Normal	Lexan cover installed over NIM bin in DAQ room		05/12/2015 03:32 PM
8758	Necessary Maintenance	New	Normal	Decision about separating Mpod HV and LV modules into different crates		05/12/2015 03:31 PM
8757	Necessary Maintenance	New	Normal	Mpod LV module need to be tested		05/12/2015 03:25 PM
8756	Necessary Maintenance	New	Normal	MPod HV modules need to be tested		05/12/2015 03:20 PM
8753	Necessary Maintenance	New	Normal	Spare Wiener PL508 power supplies need to be load-tested		05/12/2015 03:15 PM
8748	Necessary Maintenance	Accepted	Normal	Drift HV cable flange needs to be secured	Sarah Lockwitz	06/02/2015 10:44 AM
8747	Necessary Maintenance	New	Normal	Establish final length of HV drift cable	Sarah Lockwitz	05/12/2015 03:08 PM
8746	Necessary Maintenance	New	Normal	Connect HV drift cable from cryostat to filter pot	Sarah Lockwitz	05/12/2015 03:07 PM
8745	Necessary Maintenance	New	Normal	Connect PMT HV cables to PMT HV modules	Taritree Wongjirad	05/12/2015 03:05 PM
8744	Necessary Maintenance	Resolved	Normal	Connect PMT cables to PMT flange	Taritree Wongjirad	10/09/2015 08:42 AM
8743	Necessary Maintenance	New	Normal	Write up summary and conclusions from mock TPC tests at DAB	Jonathan Asaadi	05/15/2015 06:31 AM
8742	Necessary Maintenance	New	Normal	Write up summary and conclusions from remote viewing inside cryostat		05/12/2015 03:03 PM
8741	Necessary Maintenance	New	Normal	Set up control room computer screens	Joseph Zennamo	05/19/2015 10:13 AM
8740	Bug	Resolved	Urgent	Eliminate cause of Vole-like chirping occurring on most channels when HV wire bias is turned on	Michael Mooney	10/22/2015 12:51 PM
8739	Necessary Maintenance	New	Normal	Remove HV filter boxes from back of MPod		05/12/2015 02:57 PM
8738	Necessary Maintenance	New	Normal	Develop Cryo Display in ROC-W		05/12/2015 02:54 PM
8737	Necessary Maintenance	New	High	Hardware history database		05/14/2015 02:37 PM
8736	Necessary Maintenance	New	Normal	MPod HV modules need to be labelled		05/12/2015 02:50 PM
8735	Necessary Maintenance	New	Normal	MPod LV modules need to be labelled		05/12/2015 02:49 PM
8734	Necessary Maintenance	New	Normal	PMT HV modules need to be labelled	Taritree Wongjirad	05/12/2015 02:49 PM
8731	Necessary Maintenance	New	Normal	Label cable from PMT/laser interlock box to PMT HV interlock input	Taritree Wongjirad	05/12/2015 02:35 PM
8728	Necessary Maintenance	New	Normal	Write procedure to power down Drift HV rack	Sarah Lockwitz	05/12/2015 03:00 PM
8726	Necessary Maintenance	New	Normal	Install fan above PMT flange	Taritree Wongjirad	05/12/2015 02:23 PM
8725	Necessary Maintenance	New	Normal	Determine operational requirements for TPC flange FT heaters		05/12/2015 02:21 PM
8724	Necessary Maintenance	New	Normal	Purchase power plug adapter for network switches in racks on LArTF platform	Matthew Toups	05/12/2015 02:20 PM
8723	Necessary Maintenance	New	High	Put LArTF network connection on UPS		05/14/2015 02:38 PM
8722	Necessary Maintenance	Assigned	Normal	Load-balance current draw from sebs in DAQ room at LArTF	Wesley Ketchum	05/12/2015 02:13 PM
8721	Necessary Maintenance	New	Normal	Dress cables in back of uboonedaq-seb-02	Eric Church	05/12/2015 02:10 PM
8719	Necessary Maintenance	Accepted	Normal	Dress RS-232 to USB cable in back of drift HV rack	Sarah Lockwitz	06/02/2015 10:43 AM
8111	Necessary Maintenance	New	Normal	Remove 1kHz GIZMO stimulation signal	Matthew Toups	05/12/2015 03:01 PM
7707	Necessary Maintenance	Resolved	Normal	Install LED flasher board at LArTF	Taritree Wongjirad	10/09/2015 08:43 AM
7704	Necessary Maintenance	Assigned	Normal	Check out the TPC wire bias outputs and set points	Sowjanya Gollapinni	05/14/2015 02:31 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
7700	Necessary Maintenance	New	Normal	Specify voltage and supply needed for field cage ring		01/28/2015 01:58 PM