VME BPM - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
16009	Bug	Resolved	Normal	Attenuation tables won't initialize correctly on startup	John Diamond	03/28/2017 03:49 PM
15296	Task	Assigned	Normal	BBM Interface	John Diamond	01/27/2017 03:00 PM
15293	Necessary Maintenance	Resolved	Normal	Replace SBC at F4	John Diamond	01/24/2017 02:05 PM
12809	Bug	New	Normal	F4 node won't boot	John Diamond	05/27/2016 02:20 PM
12805	Bug	Resolved	High	SY BPMs won't boot	John Diamond	05/27/2016 02:19 PM
11838	Milestone	New	Normal	Release 201603A	John Diamond	03/24/2016 04:01 PM
10890	Task	Assigned	Normal	Upgrade ClassACNet/Mooc	John Diamond	02/27/2016 09:05 PM
10032	Bug	New	Normal	VP94 and HP103 show identical data when plotted together	John Diamond	09/03/2015 11:35 AM
9665	Task	New	Normal	Move scaling into the frontend	John Diamond	07/17/2015 02:49 PM
9358	Task	New	Normal	Add nodes to save list	John Diamond	07/06/2015 02:05 PM
16577	Task	New	Normal	Improve error handling of CAN bus communication		04/12/2018 09:10 AM
16576	Task	New	Normal	Investigate reading back attenuator settings from transition crate		05/17/2017 11:16 AM
16575	Task	New	Normal	Error state during spill		05/17/2017 11:10 AM
16574	Task	New	Normal	ACNET support for beam threshold		05/17/2017 11:05 AM
16573	Task	New	Normal	Establish alarms for SBPMxx nodes		05/17/2017 10:44 AM
16572	Task	New	Normal	Put together a test stand		05/17/2017 10:38 AM
16571	Bug	New	Normal	Flat positions being reported intermittently		05/17/2017 10:36 AM
16570	Milestone	New	Normal	Improvements for auto-tune operation		05/17/2017 10:30 AM