VxWorks Kernels - Feature #12822

gige on newer 5500s does not work

05/31/2016 03:38 PM - Mike Sliczniak

Status:	Assigned		**Start date:**	05/31/2016
Priority:	Normal		**Due date:**	
Assignee:	Mike Sliczniak		**% Done:**	0%
Category:	VxWorks 6.4 / MVME-5500		**Estimated time:**	0.00 hour
Target version:				

Description

Related issues:		
Related to VxWorks Kernels - Bug #14098: Create kernel for newer MVME-5500 bo...	**Assigned**	**10/06/2016**

History

#1 - 06/08/2016 02:03 PM - Richard Neswold

- Status changed from New to Assigned

- Assignee set to Richard Neswold

#2 - 10/06/2016 11:08 AM - Richard Neswold

- Assignee changed from Richard Neswold to Mike Sliczniak

Not sure why I assigned this to me.

#3 - 09/19/2017 04:16 PM - Richard Neswold

- Related to Bug #14098: Create kernel for newer MVME-5500 boards added

#4 - 04/06/2018 03:34 PM - Richard Neswold

Mike reports he'll have the new kernel ready by our next group meeting (early May.)

#5 - 04/18/2018 01:02 PM - Richard Neswold

- Category set to VxWorks 6.4 / MVME-5500

#6 - 12/13/2018 11:10 AM - Richard Neswold

Richard Neswold wrote:

> **Mike** reports he'll have the new kernel ready by our next group meeting (early May.)

Bobby Santucci says their inventory of 5500s is now consisting of newer boards in which the ethernet doesn't work. **Mike**, you said the fixes would be in 7 months ago. Can you please get the newer boards to work?