PIP-II IT HWR - Bug #25132

The triggers for LLRF HWR are running off user defined clock events. This must be changed to 2F.

10/27/2020 09:34 AM - Shrividhyaa Sankar Raman

Status:	New		**Start date:**	10/27/2020
Priority:	Normal		**Due date:**	
Assignee:			**% Done:**	0%
Category:			**Estimated time:**	0.00 hour
Target version:			**Spent time:**	0.00 hour

Description

The triggers for LLRF HWR are running off user defined clock events. This must be changed to 2F.