uBoone Operations - Necessary Maintenance #8841

Necessary Maintenance # 8839 (New): Assign permanent port numbers to the rs232 connection

GUI laser

05/18/2015 09:58 AM - Thomas Strauss

Status:	New	**Start date:**	05/18/2015
Priority:	Normal	**Due date:**	
Assignee:	Thomas Strauss	**% Done:**	0%
Category:		**Estimated time:**	4.00 hours
Target version:		**Spent time:**	0.00 hour

Description

The UV laser GUI needs to be renamed to GUI.py and needs updates on the correct display of error message (e.g. interlock on/off). The permanent ports need to be assigned.