AD Main Injector Department - List With Due Date

#	Tracker	Status	Due date	Priority	Subject	Assignee	Updated
20643	Task	Assigned	09/30/2018	Normal	Update Recycler Orbit Main Injector Ramp Compensation	Kyle Hazelwood	08/20/2018 11:18 AM
15030	Necessary Maintenance	Resolved		Low	Need to switch to APVDB from APPDB	Kyle Hazelwood	01/06/2017 11:03 AM
14742	Feature	Accepted		High	Setting dqH and dqV to zero shoud put 0 current on 30 quad trims		12/01/2016 03:03 PM
14436	Bug	Assigned		Urgent	MI and RR_NOVA lattices very old	Kyle Hazelwood	11/07/2016 04:17 PM
14435	Bug	New		Low	Trying to plot drfit sapce betas breaks plot feature		11/07/2016 04:13 PM
13053	Bug	Assigned		Low	Remove ability to disable $20/$21 prepare for beam timer from program	Kyle Hazelwood	06/27/2016 11:13 AM
11837	Idea	New		Normal	Smoothing at profile timer 0 not as easy as it used to be	Kyle Hazelwood	02/26/2016 03:14 PM
11824	Feature	New		Normal	Ability to close on each injection		02/24/2016 03:09 PM
11823	Feature	New		Low	Ability to close to a closure offset		02/24/2016 03:07 PM
11821	Feature	New		Low	New phase trombone		12/01/2016 03:04 PM
11820	Feature	Assigned	07/01/2016	High	Add RR > P1 line closure	Kyle Hazelwood	02/24/2016 02:59 PM
11819	Bug	New		Low	Order newest files first		02/24/2016 02:56 PM
11818	Bug	New		Low	H100 position comparison wildly wrong on compare		02/24/2016 02:54 PM
11529	Bug	New		Low	Abort button does not dissapear	Kyle Hazelwood	01/28/2016 10:54 AM
11528	Bug	New		High	Need more accuracy for R50 desire file	Kyle Hazelwood	01/28/2016 10:42 AM
11526	Idea	New		Low	Remove momentum correction from program	Kyle Hazelwood	01/28/2016 10:37 AM
8687	Feature	New		Low	Increase data column count		05/08/2015 04:42 PM
8389	Bug	New		Normal	Tune setting should fail when any corrector reaches its current limit		04/21/2015 04:23 PM
8303	Idea	New		Normal	Beam-Compensation current limit		04/11/2015 10:02 PM
8298	Bug	New		Normal	Inconsistent behavior when setting anode program past "Max HV"		04/10/2015 12:38 AM
8297	Feature	New		Low	RF parameters table		04/09/2015 11:55 PM
8037	Bug	New		Normal	Booster > MI line trim calibration file needs to be updated		03/09/2015 07:46 AM
7935	Idea	New		Normal	Add RR 8 GeV line to program		02/24/2015 03:58 PM
7754	Idea	Assigned	07/01/2015	Low	Rewrite application in Java	Kyle Hazelwood	01/31/2015 10:16 PM