AD Main Injector Department

	2021-3				2021-4					2021-5				2021-6				2021-7					2021-8			
	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
AD Main Injector Department																										
Main Injector and Recycler Beam Loss Monitor (...)																										
Need to switch to APVDB from APPDB		Resolved																								
Main Injector and Recycler Lattice Data Application (...)																										
Increase data column count		New																								
Trying to plot drfit sapce betas breaks (...)		New																								
MI and RR_NOVA lattices very old		Assigned																								
Main Injector Beam Line Smoothing Application (...)																										
Add RR 8 GeV line to program		New																								
Main Injector Orbit Smoothing Application (...)																										
H100 position comparison wildly wrong (...)		New																								
Order newest files first		New																								
Smoothing at profile timer 0 not as (...)		New																								
Remove ability to disable $20/$21 prepare (...)		Assigned																								
Main Injector Radiation Survey Application (...)		Main Injector Radiation Survey Application (PA4078, I128)																								
Rewrite application in Java		Assigned																								
Main Injector RF Control Application (PA1677, (...)																										
RF parameters table		New																								
Inconsistent behavior when setting anode (...)		New																								
Recycler Injecton Closure Application (PA4187, (...)		Recycler Injecton Closure Application (PA4187, R52)																								
Booster > MI line trim calibration file (...)		New																								
Add RR > P1 line closure		Assigned																								
Ability to close to a closure offset		New																								
Ability to close on each injection		New																								
Recycler Orbit Smoothing Application (PA4196, (...)																										
Remove momentum correction from program		New																								
Need more accuracy for R50 desire file		New																								
Abort button does not dissapear		New																								

Recycler Tune Control Application (PA4208, (...)	**Recycler Tune Control Application (PA4208, R2)**
Beam-Compensation current limit	**New**
Tune setting should fail when any corrector (...)	**New**
New phase trombone	**New**
Setting dqH and dqV to zero shoud put (...)	**Accepted**
Studies	**Studies**
Update Recycler Orbit Main Injector (...)	**Assigned**