AD EE Support Department - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
23894	Feature	Resolved	Normal	MI Beam Intensity Compensation problems	Kevin Martin	01/15/2020 04:34 PM
8133	Bug	New	Normal	Bus errors occur in a cycle following a cycle of the same type which is longer the normal	Kevin Martin	03/20/2015 10:20 AM