## AD Instrumentation - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 22552 | Feature | New | Normal | Support displaying data in gnuplot | John Diamond | 05/08/2019 02:55 PM |
| 22551 | Feature | New | Normal | Support displaying bpmd broadcasts | John Diamond | 05/08/2019 02:55 PM |
| 20399 | Feature | New | Normal | Support for VME A24 | | 07/23/2018 09:16 AM |
| 17776 | Feature | New | Normal | Support for DMA transfers from DAQ modules | John Diamond | 09/26/2017 11:17 AM |
| 16345 | Feature | New | Normal | Add offset to add into waveform points | | 04/26/2017 11:48 AM |
| 13335 | Feature | New | Normal | Upgrade to VxWORKS 6.7 | Elliott McCrory | 07/25/2016 03:17 PM |
| 13333 | Feature | New | Normal | Upgrade all BPM nodes to ACNET/MOOC 4.6 | Elliott McCrory | 07/25/2016 03:11 PM |
| 12946 | Feature | New | High | MDAT requires Baseline Filter | Elliott McCrory | 10/13/2016 02:27 PM |
| 10889 | Feature | New | High | Implement Mooc 720 Hz Upgrade | Roger Tokarek | 11/09/2015 03:40 PM |
| 8947 | Feature | New | Normal | Device List in Meta | John Diamond | 05/27/2015 08:12 PM |
| 8826 | Feature | New | Normal | Camera Ordering | John Diamond | 05/27/2015 08:40 PM |
| 8559 | Feature | New | Normal | BBB standard deviation device | | 05/01/2015 09:15 AM |
| 8275 | Feature | New | Normal | Saturated Pixels incorrect on Background Subtraction | John Diamond | 04/08/2015 08:14 AM |
| 21696 | Feature | Assigned | Normal | Snapshot plot support for Booster BPMs | Elliott McCrory | 01/15/2019 12:53 PM |
| 20401 | Feature | Assigned | Normal | A24 Data Regions Support | John Diamond | 07/23/2018 09:16 AM |
| 20400 | Feature | Assigned | Normal | A24 Registers Support | John Diamond | 07/23/2018 09:16 AM |
| 19601 | Feature | Assigned | Normal | Firmware loading tool for Linux | Elliott McCrory | 04/09/2018 03:26 PM |
| 18636 | Feature | Assigned | Normal | bpmcli command to reload bpmd.conf | John Diamond | 12/29/2017 11:08 AM |
| 16050 | Feature | Assigned | Normal | Build support into Cycle Devices that can support the two groups of 8 for g-2 transfers | John Diamond | 04/03/2017 01:58 PM |
| 13694 | Feature | Assigned | Normal | Support tracking the chopper's pulse width with a static amount of extra time | John Diamond | 08/26/2016 01:38 PM |
| 13572 | Feature | Assigned | Normal | ACNET device support for new MPS features in ABB0F firmware | John Diamond | 10/25/2016 03:12 PM |
| 12791 | Feature | Assigned | Normal | Support 53MHz, 53MHz stacked and 2.5MHz transition board modes | John Diamond | 05/26/2016 01:06 PM |
| 12390 | Feature | Assigned | Normal | ACNET interface for CMTFInterlocksADC | John Diamond | 04/26/2016 07:50 PM |
| 11849 | Feature | Assigned | Normal | TSG Support | John Diamond | 03/15/2016 12:21 PM |
| 11021 | Feature | Assigned | Normal | Use Trace for logging & error reporting | John Diamond | 01/02/2016 10:07 PM |
| 11011 | Feature | Assigned | Normal | Normalized BEL devices | John Diamond | 12/14/2015 11:47 AM |
| 10985 | Feature | Assigned | Normal | Injection and Extraction Cycle Devices | John Diamond | 11/23/2015 03:08 PM |
| 10966 | Feature | Assigned | Normal | Reset sum on disarm event + delay | John Diamond | 11/20/2015 10:33 AM |
| 9396 | Feature | Assigned | Normal | Beam Energy Loss Devices | John Diamond | 01/04/2016 02:15 PM |
| 9391 | Feature | Assigned | Normal | Implement MDAT Receiver | John Diamond | 09/23/2015 04:27 PM |
| 20351 | Feature | Resolved | Normal | Support for 4-channel 2-dimensional BPMs | John Diamond | 08/22/2018 08:48 PM |

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 18037 | Feature | Resolved | Normal | Support flagging that data could not be read when a DAQ module is missing/failed | John Diamond | 10/29/2017 09:47 AM |
| 12632 | Feature | Resolved | Normal | Support new digitizer gate mode for ASTA | John Diamond | 05/13/2016 12:45 PM |
| 17771 | Feature | Work in progress | Normal | Support for flash-turn and flash-orbit measurements | John Diamond | 10/06/2017 01:02 PM |
| 11729 | Feature | Work in progress | High | 201602A Replace Latch with ATR | Elliott McCrory | 10/13/2016 02:27 PM |
| 10976 | Feature | Work in progress | Normal | Confirm ADC Present and Correct | Elliott McCrory | 10/13/2016 02:28 PM |