## AD Instrumentation - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 13371 | Support | New | Low | Replicate PXINT on NBEAM Request | Roger Tokarek | 08/03/2016 03:31 PM |
| 12616 | Support | New | Normal | Transfer MI DCCT Acnet devices from ANUB to MIDCCT | Roger Tokarek | 05/12/2016 02:04 PM |
| 12513 | Support | New | Normal | Array Data Timeout Request | Roger Tokarek | 05/04/2016 02:50 PM |
| 9877 | Support | New | Low | Re-Write "RFIES Variants - Detailed" | Roger Tokarek | 08/22/2015 03:50 PM |
| 12935 | Support | Assigned | High | DCCT: Transfer Recycler Devices from MIBEAM to ANUB | Roger Tokarek | 06/28/2016 04:42 PM |
| 18695 | Support | Resolved | Normal | State machine devices for Booster IPMs | David Slimmer | 01/08/2018 09:14 AM |
| 13359 | Support | Work in progress | Normal | Update Pxie Gate Width Calibration Mode | Roger Tokarek | 07/29/2016 09:08 AM |
| 12865 | Support | Work in progress | Normal | Pxint Firmware Update to ABB0E | Roger Tokarek | 08/03/2016 01:20 PM |
| 11758 | Support | Work in progress | Normal | 201602A Document ATR | Roger Tokarek | 08/03/2016 10:36 AM |
| 11737 | Support | Work in progress | Low | Rename *.h Files to *.hpp | | 08/03/2016 10:34 AM |