## AD Instrumentation - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 15293 | Necessary Maintenance | Resolved | Normal | Replace SBC at F4 | John Diamond | 01/24/2017 02:05 PM |
| 16553 | Necessary Maintenance | Closed | High | NMLTOR is not responding after power outage | John Diamond | 05/16/2017 11:18 AM |
| 10832 | Necessary Maintenance | Closed | Normal | Replace the sbpmsb with a MVME2434 | John Diamond | 11/09/2015 09:15 AM |
| 12056 | Necessary Maintenance | Rejected | Low | Break VMEIntCommands.cpp into Sub-Systems | Roger Tokarek | 10/13/2016 09:17 AM |