AD Instrumentation - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
6970	Bug	Closed	Normal	Network issues with nmltor		11/05/2014 10:57 AM
6980	Bug	Resolved	Normal	Live Images not working	John Diamond	05/15/2015 01:17 PM
7023	Bug	Resolved	Normal	Remember fit selection between acquisition types		05/15/2015 02:09 PM
7065	Bug	Resolved	Normal	Error notifications on multi-screen displays	John Diamond	05/15/2015 02:00 PM
8273	Bug	Resolved	High	Picture Stops Updating	John Diamond	05/15/2015 02:06 PM
8274	Bug	Accepted	Normal	Incorrect amplitude scaling on ROI	John Diamond	05/15/2015 02:03 PM
8353	Bug	New	Normal	Java Security Blocks		04/16/2015 10:25 AM
8452	Bug	Resolved	High	Input is not in the .gz format	John Diamond	05/12/2015 04:21 PM
8558	Bug	Feedback	Normal	BBB devices are returning stale data	John Diamond	06/09/2015 02:30 PM
8945	Bug	Accepted	High	Error on One-Shot Acquisition	John Diamond	06/01/2015 04:55 PM
8946	Bug	New	Normal	Defalut camera?		05/27/2015 09:10 AM
8996	Bug	New	High	Incorrect Horz Histogram window on ROI		06/01/2015 01:03 PM
9016	Bug	Closed	Normal	Remove beam intensity threshold from magnitude devices	John Diamond	07/01/2015 03:28 PM
9032	Bug	Closed	Normal	State machine task does not properly shutdown.	John Diamond	06/10/2015 02:38 PM
9073	Bug	Closed	Normal	Devices stop reporting data before the $36 event goes out	John Diamond	07/01/2015 03:28 PM
9075	Bug	Closed	Normal	Kernel panic when re-inserting btimemod	John Diamond	06/10/2015 02:38 PM
9081	Bug	Closed	Normal	Detach from TCLK events when StateMachine is destroyed	John Diamond	06/10/2015 02:38 PM
9085	Bug	Closed	Normal	VME Interrupt already taken error when re-launching bpmd	John Diamond	06/10/2015 02:37 PM
9088	Bug	New	Low	BPMDRO does not release on exit	John Diamond	06/10/2015 11:04 AM
9280	Bug	New	Normal	Turn off interrupts when module is removed.	John Diamond	06/23/2015 01:55 PM
9320	Bug	Closed	Normal	MoocNew() fails on tstbpm3	John Diamond	07/01/2015 03:28 PM
9323	Bug	Closed	Normal	Problems with vmeserver on sybpmp1	John Diamond	07/01/2015 03:27 PM
9344	Bug	Closed	Normal	Transition board channels are not properly mapped to digitizer channels.	John Diamond	07/01/2015 04:32 PM
9345	Bug	Closed	Normal	Serial port not working on sbpmf1	John Diamond	07/01/2015 03:26 PM
9347	Bug	Closed	Normal	Transition board attenuation does not change as expected.	John Diamond	07/02/2015 04:08 PM
9349	Bug	Closed	Normal	sbpmf3 is down	John Diamond	07/02/2015 10:51 AM
9355	Bug	Closed	Normal	Extra events listed for PMCUCDTimingSystem	John Diamond	11/05/2015 07:56 AM
9359	Bug	Closed	Normal	Reading garbage from I:BEAM	John Diamond	07/02/2015 04:06 PM
9613	Bug	Resolved	Normal	btimemod_device_release does not release alarm interrupt handler	John Diamond	07/14/2015 09:55 AM
9620	Bug	Rejected	Normal	Data returned by raw character device doesn't make sense	John Diamond	07/28/2015 01:09 PM
9636	Bug	Assigned	Normal	Timing board stops generating TCLK interrupts	John Diamond	11/24/2015 02:23 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
9790	Bug	Closed	Normal	Data access exception in transition board control task	John Diamond	08/07/2015 02:30 PM
9939	Bug	Closed	Normal	Digitizers at SSB have the wrong firmware.	John Diamond	08/28/2015 09:43 AM
10026	Bug	Closed	Normal	Program exception in bpmShowSlowBuffer shell-command	John Diamond	09/04/2015 12:40 PM
10032	Bug	New	Normal	VP94 and HP103 show identical data when plotted together	John Diamond	09/03/2015 11:35 AM
10044	Bug	Closed	Normal	Some BPMs are incorrectly mapped for TG9	John Diamond	09/04/2015 12:39 PM
10049	Bug	Closed	Normal	TB getting garbage attenuation values on most cycles (but not all!)	John Diamond	09/04/2015 12:39 PM
10094	Bug	New	Normal	Frequent Errors in Live Acquisition		10/02/2015 11:40 AM
10405	Bug	Closed	Normal	VMEServer Not Working	Roger Tokarek	11/22/2015 10:54 AM
10427	Bug	Closed	Immediate	Provide correct A32 Addressing	Roger Tokarek	11/22/2015 10:53 AM
10496	Bug	Closed	Urgent	MI TOROID R:TOR703 (S60TOR) Drop Outs	Roger Tokarek	11/22/2015 10:52 AM
10980	Bug	Closed	Normal	Test MirrTorDrv on S60	Roger Tokarek	11/23/2015 10:33 AM
11005	Bug	Closed	Normal	Artesyn Board VmeA32ToLocalArtesyn() Not Working	Roger Tokarek	11/25/2015 03:20 PM
11233	Bug	Closed	High	Update TOD Tasks in PXINT and NMLTOR Startup	Roger Tokarek	08/03/2016 10:22 AM
11241	Bug	Closed	High	Create NMLTOR Variant	Roger Tokarek	10/13/2016 02:29 PM
11256	Bug	Closed	Normal	Assign ssdn device ID for ScaleFilter Access	Roger Tokarek	08/03/2016 10:24 AM
11275	Bug	Closed	Normal	anub is randomly crashing once every few days	John Diamond	01/06/2016 01:11 PM
11458	Bug	New	Normal	Camera-Switch Instability		01/20/2016 06:12 PM
11719	Bug	Closed	Normal	Raw pulse data should only readout the number of samples that were digitized	John Diamond	02/28/2016 06:38 PM
11945	Bug	Closed	High	Resolve Task Runtime Error	Roger Tokarek	08/03/2016 10:41 AM
11946	Bug	New	Normal	Scale Factor EVENT OVERLAP Error Message	John Diamond	03/11/2016 03:44 PM
11996	Bug	Work in progress	High	Remove Conditional Compilation for Addressing	Roger Tokarek	08/03/2016 10:54 AM
12497	Bug	Closed	Urgent	Investigate Possible Pxie Current vs Current Average Discrepancy	Roger Tokarek	08/03/2016 01:09 PM
12749	Bug	Work in progress	Low	Cleanup DcctDrv & Calls to DcctDrv	Roger Tokarek	08/03/2016 01:16 PM
12753	Bug	Resolved	Normal	80MHz board driver could be a little more forgiving of mistakes.	John Diamond	05/23/2016 02:38 PM
12754	Bug	New	Normal	slowness of init of 80MHz driver ??	John Diamond	05/23/2016 02:18 PM
12763	Bug	Accepted	Normal	Raw data device does not support channels	John Diamond	05/25/2016 12:17 PM
12805	Bug	Resolved	High	SY BPMs won't boot	John Diamond	05/27/2016 02:19 PM
12809	Bug	New	Normal	F4 node won't boot	John Diamond	05/27/2016 02:20 PM
12915	Bug	Assigned	High	Missing first injection and other odd behavior with 6+6 slip stacking state	John Diamond	06/27/2016 02:23 PM
12929	Bug	Work in progress	Normal	Pxie Scrapers Clean Up	Roger Tokarek	08/03/2016 03:27 PM
13314	Bug	Closed	Normal	Set A32 Address Pointer to 0x0	Roger Tokarek	08/03/2016 03:29 PM
13456	Bug	Resolved	Normal	80MHz Digitizer requires repeating commands for re-arming twice	Dennis Nicklaus	08/05/2016 03:10 PM
13457	Bug	Resolved	Normal	80MHz digitizer driver should sanity check Nchannels setting	Dennis Nicklaus	08/05/2016 03:03 PM

#	Tracker	Status	Priority	Subject	Assignee	Updated
13462	Bug	New	Normal	57 -97 errors on raw/triggered data channels > 6		08/05/2016 03:14 PM
15282	Bug	New	Normal	Support plotting MDAT transmitter frames via ACNET	Elliott McCrory	01/23/2017 04:07 PM
16009	Bug	Resolved	Normal	Attenuation tables won't initialize correctly on startup	John Diamond	03/28/2017 03:49 PM
16571	Bug	New	Normal	Flat positions being reported intermittently		05/17/2017 10:36 AM
17746	Bug	Rejected	Normal	Segfault every other time Acsys is restart		10/18/2017 08:19 PM
18197	Bug	New	Normal	Why do soft reboots sometime hang?		11/10/2017 10:14 AM
18630	Bug	Closed	Normal	R 104 H IPM plotting abnormalities	Elliott McCrory	10/17/2018 01:24 PM
18632	Bug	New	Normal	Single turn plot does not work when plotting a turn lower than #1534 and with auto-scaling ON	Elliott McCrory	12/28/2017 09:16 AM
18633	Bug	Closed	Normal	Data save files no longer being saved?	Elliott McCrory	10/17/2018 01:27 PM
18635	Bug	Resolved	High	Necessary LabView parameters are no longer fast time plottable.	David Slimmer	01/08/2018 07:47 AM
18755	Bug	New	Normal	Plotting Charge, Sigma and Turns does not scale to # Turns Analyzed.	Elliott McCrory	01/19/2018 09:25 AM
18773	Bug	Resolved	Normal	Single turn plot not showing current data until you toggle single turn -> charge plot -> single turn	David Slimmer	01/26/2018 03:32 PM
19502	Bug	New	Normal	Excessive delay in first plot, capturing ACNET cursor in window	Elliott McCrory	03/26/2018 02:32 PM
20371	Bug	Assigned	Normal	TSI-148 bridge does not support a master window with multiple data transfer modes	John Diamond	07/23/2018 11:07 AM
20402	Bug	Resolved	Normal	Constants generated for bitfields and enums can cause redeclaration	John Diamond	07/23/2018 10:30 AM
20408	Bug	Resolved	Normal	runtime_error in generated getDeviceInSlot() does not include the driver name	John Diamond	07/23/2018 11:27 AM
20432	Bug	Work in progress	Normal	Kernel-level xxxmod_device_get() routine has bbpm250x12 hard-coded	John Diamond	07/24/2018 03:00 PM
20450	Bug	New	Normal	The number of samples argument to bpmcli dump does not respect multiple bunches		07/25/2018 03:47 PM
20473	Bug	Resolved	Normal	Control message queue is not destroyed on shutdown	John Diamond	07/28/2018 08:27 PM
23334	Bug	New	Normal	Review request [commit:9d6fb8c32be2b760ee703095242308551c178991: Removed commented syslog(..) calls that where replaced with TRACE.]		09/25/2019 03:06 PM
24142	Bug	Closed	Normal	A pointer is de referenced before checking it to NULL in remove()	Robert Santucci	03/17/2020 10:45 AM
24143	Bug	New	Normal	Missing Mutual Exclusion with linked list internals	Robert Santucci	03/06/2020 11:47 AM