CAMAC - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
23153	Support	Assigned	Normal	Write DABBEL template for 473 devices	Richard Neswold	08/21/2019 11:18 AM
15854	Support	Assigned	Normal	CAMAC front-ends need to use 720Hz clock delivery support	Richard Neswold	03/14/2017 09:33 AM
14513	Support	Assigned	Low	Clean-up serial ports on camcon.fnal.gov	Richard Neswold	12/15/2016 01:37 PM
12409	Support	Assigned	High	Extend C1151 driver to include reading	Richard Neswold	05/10/2016 10:31 AM
8161	Support	Assigned	Normal	Upgrade the CAMAC front-ends to VxWorks 6.x and the SLE	Richard Neswold	03/24/2015 10:09 AM
8125	Support	Assigned	Normal	Upgrade the beamline front-ends to frontend.mk and MOOC 4.6	Richard Neswold	10/23/2018 04:42 PM