darkside - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
7216	Feature	Resolved	Normal	Add "hybrid" options to the veto-choice parameter in the SystemWithVeto scripts	Kurt Biery	10/24/2014 03:17 PM
7215	Feature	Resolved	Normal	Add the ability to specify TDC pulse delay and gate width parameters in the manageSystemWithVeto.sh script	Kurt Biery	10/24/2014 03:15 PM
7063	Feature	Resolved	Normal	Add carriage returns to lines in the FCL files that are generated with manageXYZ -v	Kurt Biery	09/24/2014 10:24 AM
6842	Feature	Resolved	Normal	Add parameters to V1495 fhicl files	Kurt Biery	09/24/2014 10:47 AM
6840	Feature	Assigned	Normal	Add control of the inhibit time to manageSystemWithVeto.sh, etc.	Kurt Biery	09/25/2014 08:37 AM
6837	Feature	Resolved	Normal	Add command-line options to the control scripts to enable/disable V1724 boards	Kurt Biery	09/25/2014 08:36 AM
6835	Feature	Assigned	Normal	Update to art v1_12_xx	Kurt Biery	10/09/2014 08:59 AM
4897	Feature	New	Normal	Allow FHiCL configuration of DB port in DBInterface.		04/23/2014 01:13 PM
4529	Feature	New	Normal	Create a tool to verify that DAQ nodes are running and accessible over Infiniband		04/23/2014 01:31 PM
4503	Feature	Assigned	Normal	Make use of the new file naming features in art	Kurt Biery	04/23/2014 01:34 PM
4363	Feature	New	High	Allow art modules to be disabled/enabled [art-related]	Kurt Biery	04/23/2014 01:38 PM
4362	Feature	Accepted	High	Provide a hook within art to allow moving a completed, closed data file to a different directory [art-related]	Kurt Biery	04/23/2014 01:40 PM
4358	Feature	Resolved	Normal	Provide configurable file naming within art [art-related]	Kurt Biery	08/06/2013 08:40 AM
4354	Feature	New	Normal	Avoid situations in which exceptional conditions in online monitoring module cause DAQ processes to crash [art-related]		07/17/2013 09:30 AM
4353	Feature	New	High	Ensure that disk files always get closed no matter how the DAQ is shut down [art-related]	Kurt Biery	07/17/2013 10:02 AM
4316	Feature	New	Normal	Add the ability to exclude a specific PMT from the majority logic trigger		04/25/2014 04:13 PM
4300	Feature	New	Normal	Investigate why events come in bursts (on a short time scale)		04/25/2014 03:00 PM
4239	Feature	New	Normal	Implement (or deploy) a scheme to archive log files on the DAQ cluster		04/25/2014 04:14 PM
4167	Feature	New	Normal	Remove the retries of the 1495 IRQ writes after the new firmware goes live		06/19/2013 04:37 PM
4079	Feature	New	Normal	Run extensive tests of init-start-stop-etc command sequences		04/25/2014 04:20 PM
3958	Feature	New	Normal	Continue running when online monitoring is requested but the XPRA server is not running		04/25/2014 03:57 PM
3951	Feature	New	Normal	Provide the ability to select single-line MessageFacility messages	Michael Wang	06/14/2013 05:30 PM
3941	Feature	New	Normal	Allow the number of V1720 buffers to be set from ds50MasterControl		04/25/2014 03:52 PM
3940	Feature	New	Normal	Improve error reporting when the NetMonOutput_moduel buffer size is too small		04/25/2014 03:49 PM
3935	Feature	New	Normal	Rework the DS50Compression and DS50Decompression art modules to support both 1720 and 1724 data?		04/25/2014 03:03 PM
3934	Feature	Assigned	Normal	Investigate whether an Init command sent while the system is running causes the DAQ processes to stop the run in the correct order	Kurt Biery	07/08/2013 11:02 AM