drvgen - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
19604	Task	New	Normal	Remove redundant or unnecessarily long references from template code	Elliott McCrory	04/11/2018 12:09 PM
20371	Bug	Assigned	Normal	TSI-148 bridge does not support a master window with multiple data transfer modes	John Diamond	07/23/2018 11:07 AM
20399	Feature	New	Normal	Support for VME A24		07/23/2018 09:16 AM
20400	Feature	Assigned	Normal	A24 Registers Support	John Diamond	07/23/2018 09:16 AM
20401	Feature	Assigned	Normal	A24 Data Regions Support	John Diamond	07/23/2018 09:16 AM
20402	Bug	Resolved	Normal	Constants generated for bitfields and enums can cause redeclaration	John Diamond	07/23/2018 10:30 AM
20408	Bug	Resolved	Normal	runtime_error in generated getDeviceInSlot() does not include the driver name	John Diamond	07/23/2018 11:27 AM
20432	Bug	Work in progress	Normal	Kernel-level xxxmod_device_get() routine has bbpm250x12 hard-coded	John Diamond	07/24/2018 03:00 PM
20436	Task	Work in progress	Normal	Make the VME A16 scanning increment configurable	John Diamond	07/24/2018 04:06 PM