inst-bpm - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
12418	Task	New	Normal	Boot flash for PXIE BPM test stand node	John Diamond	04/29/2016 11:14 AM
12417	Task	Assigned	Normal	Network connection and kerberos principles for PXIE BPM system	John Diamond	04/29/2016 10:23 AM
12416	Milestone	New	Normal	PXIE BPM Test Node		04/29/2016 11:14 AM
12415	Milestone	New	Normal	PXIE BPM Deployment		04/29/2016 11:14 AM
9686	Task	New	Normal	Rename the IDLE command the EXIT command.	John Diamond	07/21/2015 08:20 PM
9685	Task	New	Normal	Move the Command and CommandList edit() methods into their own class	John Diamond	07/21/2015 08:14 PM
9684	Task	New	Normal	Use the GoF State pattern in StateMachine class	John Diamond	07/21/2015 08:11 PM
9683	Milestone	New	Normal	StateMachine refactor	John Diamond	07/21/2015 08:19 PM
9658	Task	New	Normal	Instrument bpmd control commands and display their execution time in syslog	John Diamond	07/20/2015 04:03 PM
9636	Bug	Assigned	Normal	Timing board stops generating TCLK interrupts	John Diamond	11/24/2015 02:23 PM
9635	Task	Feedback	Normal	Make Synoptic pages for displaying DDC data	John Diamond	07/22/2015 01:14 PM
9613	Bug	Resolved	Normal	btimemod_device_release does not release alarm interrupt handler	John Diamond	07/14/2015 09:55 AM
9610	Task	New	Normal	Test command list for reading out down converter	John Diamond	07/23/2015 04:56 PM
9609	Task	New	Normal	bpmcli command for loading the booster frequency curve from file	John Diamond	07/13/2015 04:24 PM
9608	Milestone	New	Normal	Down Converter Test	John Diamond	11/24/2015 02:23 PM
9470	Task	New	Normal	Find a replacement for the CT VX405/04x SBC	John Diamond	08/13/2015 01:53 PM
9385	Task	New	Normal	State Machine subsystem test	John Diamond	07/20/2015 04:03 PM
9383	Task	New	Normal	Implement timer-triggered commands	John Diamond	11/24/2015 02:22 PM
9280	Bug	New	Normal	Turn off interrupts when module is removed.	John Diamond	06/23/2015 01:55 PM
9250	Task	Assigned	Normal	Execute CommandLists	John Diamond	07/09/2015 04:29 PM
9153	Task	New	Normal	Design ACNET interface for command lists	John Diamond	07/21/2015 08:16 PM
9101	Milestone	New	Normal	adc250x12xs VXS interface	John Diamond	06/10/2015 02:35 PM
9017	Milestone	Accepted	Normal	State Machine subsystem	John Diamond	07/21/2015 08:16 PM
9014	Task	Accepted	Normal	Booster frequency curve	John Diamond	06/02/2015 04:38 PM
9013	Task	Accepted	Normal	Refactor pointer usage to smart pointers	John Diamond	06/10/2015 04:51 PM
9088	Bug	New	Low	BPMDRO does not release on exit	John Diamond	06/10/2015 11:04 AM