inst-bpm - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
9636	Bug	Assigned	Normal	Timing board stops generating TCLK interrupts	John Diamond	11/24/2015 02:23 PM
9620	Bug	Rejected	Normal	Data returned by raw character device doesn't make sense	John Diamond	07/28/2015 01:09 PM
9613	Bug	Resolved	Normal	btimemod_device_release does not release alarm interrupt handler	John Diamond	07/14/2015 09:55 AM
9280	Bug	New	Normal	Turn off interrupts when module is removed.	John Diamond	06/23/2015 01:55 PM
9088	Bug	New	Low	BPMDRO does not release on exit	John Diamond	06/10/2015 11:04 AM
9085	Bug	Closed	Normal	VME Interrupt already taken error when re-launching bpmd	John Diamond	06/10/2015 02:37 PM
9081	Bug	Closed	Normal	Detach from TCLK events when StateMachine is destroyed	John Diamond	06/10/2015 02:38 PM
9075	Bug	Closed	Normal	Kernel panic when re-inserting btimemod	John Diamond	06/10/2015 02:38 PM
9032	Bug	Closed	Normal	State machine task does not properly shutdown.	John Diamond	06/10/2015 02:38 PM