llrf-hwr-2cavity-firmware - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
24711	Bug	New	Normal	ADC alignment on start up	Philip Varghese	08/04/2020 04:59 PM
24596	Bug	Work in progress	Normal	Resonance control goes with the wrong controller	Philip Varghese	07/10/2020 11:48 AM