Machine Protection - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
19472	Support	Closed	Normal	Changes to the frequency device.	Richard Neswold	04/04/2018 10:28 AM
19131	Support	Closed	High	Add another ring pickup to the loss monitor task	Richard Neswold	03/15/2018 03:38 PM
19130	Support	Closed	Normal	Finish PECI driver	Richard Neswold	03/13/2018 02:03 PM
12363	Support	Closed	Normal	BLMs in SRFBLM front-end return [57 -77]	Richard Neswold	04/20/2016 11:09 AM
12065	Support	Closed	Normal	Rename devices in SRFMPS	Richard Neswold	03/25/2016 02:30 PM
11834	Support	Closed	Normal	PXIMPS Processor board doesn't boot reliably.	Richard Neswold	11/09/2017 10:54 AM
11527	Support	Closed	Normal	The V1495 card, used in PXIMPS, added registers	Richard Neswold	01/28/2016 10:45 AM