DAQ - Unassigned Issues

#	Project	Tracker	Status	Subject	Author	Updated
CRV FEB test software (3)						
23120	CRV FEB test software	Bug	New	I put in temporary host-based ramp speed limit, should be optional	Glenn Horton-Smith	08/14/2019 12:00 PM
23119	CRV FEB test software	Bug	New	Thinks all bias calibrations are bad	Glenn Horton-Smith	08/14/2019 11:57 AM
23118	CRV FEB test software	Feature	New	No identification of bad bias or mux on display	Glenn Horton-Smith	08/14/2019 11:56 AM
PCIe linux kernel module (1)						
22484	PCIe linux kernel module	Feature	Resolved	prepare for kernel upgrade	Ron Rechenmacher	05/01/2019 11:22 AM