DAQ - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
24745	Bug	New	Normal	PV removed when added after switch to Live mode	Antonio Gioiosa	08/11/2020 06:28 AM
23120	Bug	New	Normal	I put in temporary host-based ramp speed limit, should be optional		08/14/2019 12:00 PM
23119	Bug	New	Normal	Thinks all bias calibrations are bad		08/14/2019 11:57 AM