rbpm - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
12791	Feature	Assigned	Normal	Support 53MHz, 53MHz stacked and 2.5MHz transition board modes	John Diamond	05/26/2016 01:06 PM
12768	Task	Assigned	Normal	ACNET devices for ubpm23 BPMs	John Diamond	06/02/2016 01:09 PM
12750	Task	Assigned	Normal	Configure startup scripts for ubpm6s, ubpmf1 and ubpmf23	John Diamond	05/23/2016 11:28 AM
12739	Task	New	Normal	Network connections for new muon BPM nodes	John Diamond	05/20/2016 02:17 PM
12738	Milestone	New	Normal	Commission Muon Houses S60, F1 and F23	John Diamond	06/02/2016 01:09 PM
9889	Task	Assigned	Normal	Verify test node	John Diamond	09/18/2015 11:42 AM
9888	Task	Assigned	Normal	Add test node to R143	John Diamond	09/18/2015 10:25 AM
9883	Milestone	Assigned	Normal	Setup test node	John Diamond	09/18/2015 10:25 AM