## TCLK Infrastructure - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 23813 | Bug | Assigned | Normal | System time occasionally jumps ahead by a second when using IP-UCD | Richard Neswold | 12/30/2019 12:51 PM |
| 20304 | Bug | New | Normal | libpmctrig-3.2 seems to cause failures on NBPMOV | Richard Neswold | 07/11/2018 03:28 PM |
| 20113 | Feature | Assigned | Normal | Support the extended clock specification | Richard Neswold | 06/07/2018 10:45 AM |
| 19689 | Bug | Assigned | Normal | UCD timestamps only work for 15 Hz configurations | Richard Neswold | 05/01/2018 03:04 PM |
| 19688 | Bug | Assigned | Normal | Sync event isn't last in multicast packet | Richard Neswold | 04/13/2018 04:42 PM |