## uBoone Operations - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|---|---|---|---|---|---|---|
| 8332 | Bug | Closed | High | Add more Wiener channels to archiver | Glenn Horton-Smith | 04/13/2015 08:26 PM |
| 8989 | Bug | Closed | Normal | Archived data not shown on rack fan speed and temperature panels | Glenn Horton-Smith | 06/01/2015 10:52 AM |
| 8990 | Bug | Closed | Normal | Cannot acknowledge alarms after update to new version of control system gui | Glenn Horton-Smith | 06/01/2015 10:51 AM |
| 8179 | Bug | Closed | Normal | On slowmon CSS overview panel, fix order of LSR1, LSR2, PM3, and Cryo racks | Glenn Horton-Smith | 04/16/2015 11:03 AM |
| 9038 | Bug | Closed | Normal | Relax Major/Minor low alarm for calibration channels to 0.4A instead of 0.5A | Glenn Horton-Smith | 06/05/2015 10:14 PM |
| 9037 | Bug | Closed | Normal | Relax the MINOR High/low alarm range on TPCPS LV modules 1 through 6 | Glenn Horton-Smith | 06/05/2015 10:14 PM |
| 9077 | Bug | Closed | Normal | Remove DAQ status from alarm tree temporarily | Glenn Horton-Smith | 06/09/2015 09:47 AM |
| 9035 | Bug | Closed | Normal | remove non-existant rack air temperature variables from EPICS DB | Glenn Horton-Smith | 06/05/2015 10:13 PM |
| 9021 | Bug | Closed | Normal | Remove non-existent fan pack from slow controls for ELIZabeth and TPC5 racks | Glenn Horton-Smith | 06/05/2015 10:12 PM |
| 9048 | Bug | Closed | Normal | Remove spare TPC PS LV channels from the Alarm system | Glenn Horton-Smith | 10/02/2015 02:40 PM |
| 8915 | Bug | Closed | Normal | Time on redmine server | Michael Kirby | 06/05/2015 07:46 AM |