

0x00000000 0x00003FC	TCLK Event Option Memory	LONGWORD	R/W	Cs0
0x00008000 0x000083FC	BSYNC Event Option Memory	LONGWORD	R/W	Cs0
0x00010380	Int Pending Register	8-BITS	R/W	Cs2
0x00010400	Status	LONGWORD	R/W	
0x00010440	Command & Control	LONGWORD	R/W	
0x00018000 0x000183FC	MDAT Memory	16-BITS	R/W	Cs0
0x00020020	MDAT Interrupt Type	8-BITS	R/W	
0x0002002C	PPG Trig Source	8-BITS	R/W	Cs1
0x00020030	RF Clock Source	8-BITS	R/W	Cs1
0x00020034	PPG Free Run	1-BIT	R/W	Cs1
0x0002003C	P2 Output Enable	8-BITS	R/W	Cs1
0x00020040	PPG Begin Address	LONGWORD	R/W	Cs1
0x00020044	PPG End Address	LONGWORD	R/W	Cs1
0x00020048	PPG Lap Count	LONGWORD	R/W	Cs1
0x0002004C	Read Current Lap	LONGWORD	R/W	
0x00020050	Enable PPG Trigger	8-BITS	R/W	
0x00020054	Enable Free Run	8-BITS	R/W	
0x00020058	Force PPG Trigger	1-BIT	R/W	
0x0002005C	Clear All PPG	XXXX	W	
0x00020080	Delay Timers Enable	8-BITS	R/W	
0x00020100	Pulse Delay Zero			
0x00020108	Running Pulse Delay Zero			
0x00020120	Pulse Delay One			
0x00020128	Running Pulse Delay One			
0x00020140	Pulse Delay Two			
0x00020148	Running Pulse Delay Two			
0x00020160	Pulse Delay Three			
0x00020168	Running Pulse Delay Three			

0x00040000 0x0007FFFC	PPG Memory 64K	LONGWORD	R/W	Cs2

E:\Users\mcclure\Documents\AddressMapNewVRFT_MountainRangeScope.docx