

VME Intensity Monitor - Bug #10427

Milestone # 9388 (New): 2015 Shutdown

Provide correct A32 Addressing

10/08/2015 04:47 PM - Roger Tokarek

Status:	Closed	Start date:	10/07/2015
Priority:	Immediate	Due date:	10/08/2015
Assignee:	Roger Tokarek	% Done:	100%
Category:		Estimated time:	4.00 hours
Target version:		Spent time:	4.00 hours
Description			
Correct A32 addressing to account for board type and kernel, Motorola or Artesyn. See A32 mapping for more information. Effort complete, implemented variants to account for the different A32 Maps and modified torDrvBBB to add VmeA32ToLocalArtesyn().			

History

#1 - 11/22/2015 10:53 AM - Roger Tokarek

- Status changed from New to Closed

Resolved and completed.