

Main Injector Orbit Smoothing Application (PA1666, I50) - Bug #13053

Remove ability to disable \$20/\$21 prepare for beam timer from program

06/27/2016 11:12 AM - Kyle Hazelwood

Status:	Assigned	Start date:	06/27/2016
Priority:	Low	Due date:	
Assignee:	Kyle Hazelwood	% Done:	0%
Category:		Estimated time:	2.00 hours
Target version:		Spent time:	0.00 hour
Description			
The Operators accidentally removed the \$20 from the MI prepare for beam timer while doing I50 training. We did not have BLM losses on the \$20 all weekend because of this. I can see no reason to have this feature in I50 so it will be removed.			

History

#1 - 06/27/2016 11:13 AM - Kyle Hazelwood

Elog entry: <https://www-bd.fnal.gov/Elog/?entryIDs=87090&logNames=Main+Injector%2C+Recycler>

Files

2016-06-27.11.08.53.691.png	11.4 KB	06/27/2016	Kyle Hazelwood
-----------------------------	---------	------------	----------------