

## Main Injector Orbit Smoothing Application (PA1666, I50) - Bug #13053

### Remove ability to disable \$20/\$21 prepare for beam timer from program

06/27/2016 11:12 AM - Kyle Hazelwood

<b>Status:</b>	Assigned	<b>Start date:</b>	06/27/2016
<b>Priority:</b>	Low	<b>Due date:</b>	
<b>Assignee:</b>	Kyle Hazelwood	<b>% Done:</b>	0%
<b>Category:</b>		<b>Estimated time:</b>	2.00 hours
<b>Target version:</b>		<b>Spent time:</b>	0.00 hour
<b>Description</b>			
The Operators accidentally removed the \$20 from the MI prepare for beam timer while doing I50 training. We did not have BLM losses on the \$20 all weekend because of this. I can see no reason to have this feature in I50 so it will be removed.			

#### History

#1 - 06/27/2016 11:13 AM - Kyle Hazelwood

Elog entry: <https://www-bd.fnal.gov/Elog/?entryIDs=87090&logNames=Main+Injector%2C+Recycler>

#### Files

2016-06-27.11.08.53.691.png	11.4 KB	06/27/2016	Kyle Hazelwood
-----------------------------	---------	------------	----------------