

Instrumentation Drivers - Bug #13457

80MHz digitizer driver should sanity check Nchannels setting

08/05/2016 11:49 AM - Dennis Nicklaus

Status:	Resolved	Start date:	08/05/2016
Priority:	Normal	Due date:	
Assignee:	Dennis Nicklaus	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
The driver should ensure the setting is in the range 1-16. It doesn't now so one can set nonsensical values. Perhaps other fields should also be checked (e.g. NSamples)?			

History

#1 - 08/05/2016 03:03 PM - Dennis Nicklaus

- Status changed from Assigned to Resolved

Fixed with git commit of 8/5/2016