

artdaq Utilities - Feature #15619

Include scripts to help determine correct value for TCP receive buffers

02/21/2017 02:27 PM - Eric Flumerfelt

Status:	New	Start date:	02/21/2017
Priority:	Normal	Due date:	
Assignee:	Ron Rechenmacher	% Done:	0%
Category:	artdaq-utilities	Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Experiment:	-	Co-Assignees:	
Description			
The TCPSocket_transfer class uses either a manually-set receive buffer or the kernel autotuning. We should provide scripts/tools to help determine the correct manual setting for a given DAQ environment.			