

VME BPM - Milestone #16570

Improvements for auto-tune operation

05/17/2017 10:30 AM - John Diamond

Status:	New	Start date:	05/17/2017
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
Requested improvements in order to operate SY BPMs with Auto Tune.			
Subtasks:			
Bug # 16571: Flat positions being reported intermittently			New
Task # 16572: Put together a test stand			New
Task # 16573: Establish alarms for SBPMxx nodes			New
Task # 16574: ACNET support for beam threshold			New
Task # 16575: Error state during spill			New
Task # 16576: Investigate reading back attenuator settings from transition crate			New
Task # 16577: Improve error handling of CAN bus communication			New