

adinstbpm - Task #20704

Milestone # 20540 (New): Booster BPM deployment

Change node name for all BBPM18 devices

08/28/2018 08:05 PM - John Diamond

Status:	Resolved	Start date:	08/28/2018
Priority:	Normal	Due date:	
Assignee:	John Diamond	% Done:	100%
Category:		Estimated time:	2.00 hours
Target version:		Spent time:	0.00 hour
Description			

History

#1 - 08/28/2018 08:05 PM - John Diamond

- Status changed from New to Resolved

- % Done changed from 0 to 100

Re-assigned the node name for all B: devices on BBPM18 to BBPL18. DABEL output:

```
clx50$ dabbel bbpm18-modify.dbl
DABEL: defaulting to syntax-checking mode
DABEL: Checking file in Syntax-Checking-Only mode
DABEL: Checking file in Syntax-Checking-Only mode
! DABEL V8.05 running on file bbpm18-modify.dbl
!
!
! No syntax errors found
clx50$ dabbel bbpm18-modify.dbl modify --stdout
! DABEL V8.05 running on file bbpm18-modify.dbl
!
Device B:18BPMN      modified successfully
Device B:18COH1     modified successfully
Device B:18CORP     modified successfully
Device B:18FLH1     modified successfully
Device B:18HOFF     modified successfully
Device B:18QFLS     modified successfully
Device B:18QORB     modified successfully
Device B:B18NUM     modified successfully
      but duplicate SSDN devices found for property(s):
      PREAD
      Device(s) include:      B:18BPMN
Device B:HP18L      modified successfully
Device B:HP18S      modified successfully
Device B:HP19L      modified successfully
Device B:HP19S      modified successfully
Device B:HP20L      modified successfully
Device B:HP20S      modified successfully
Device B:HST18L     modified successfully
Device B:HST18S     modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST18L
Device B:HST19L     modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST18L      and B:HST18S
Device B:HST19S     modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
      Device(s) include:      B:HST18L      and B:HST18S
Device B:HST20L     modified successfully
      but duplicate SSDN devices found for property(s):
      PRBCTL PRBSTS
```

```

Device(s) include:      B:HST18L      and B:HST18S
Device B:HST20S      modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VP18L      modified successfully
Device B:VP18S      modified successfully
Device B:VP19L      modified successfully
Device B:VP19S      modified successfully
Device B:VP20L      modified successfully
Device B:VP20S      modified successfully
Device B:VST18L     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VST18S     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VST19L     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VST19S     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VST20L     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
Device B:VST20S     modified successfully
but duplicate SSDN devices found for property(s):
PRBCTL PRBSTS
Device(s) include:      B:HST18L      and B:HST18S
!
! Database modified with following statistics:
!      32 devices modified
!
!**Fast_FTD_Noted: device with rate > 1 Hz
!
!**duplicate SSDN properties found
The file stdout does not exist.
The file stdout does not exist.

```