

uBoone Operations - Bug #9021

Remove non-existent fan pack from slow controls for ELIZabeth and TPC5 racks

06/03/2015 11:44 AM - Glenn Horton-Smith

Status:	Closed	Start date:	06/03/2015
Priority:	Normal	Due date:	
Assignee:	Glenn Horton-Smith	% Done:	100%
Category:	slow monitoring and control	Estimated time:	0.50 hour
Target version:		Spent time:	0.50 hour
Description			

History

#1 - 06/03/2015 11:46 AM - Glenn Horton-Smith

- Category set to slow monitoring and control

#2 - 06/04/2015 03:31 AM - Sowjanya Gollapinni

- Subject changed from Remove non-existent fan pack from slow controls for ELIZabeth crate to Remove non-existent fan pack from slow controls for ELIZabeth and TPC5 racks

LIZ rack has no fan packs: remove all fans for this rack
TPC5 only has one fan pack. Remove the other 6 non-existent fans for TPC5.
uB_RackFans_TPC5_2_0/speed
uB_RackFans_TPC5_2_1/speed
uB_RackFans_TPC5_2_2/speed
uB_RackFans_TPC5_2_3/speed
uB_RackFans_TPC5_2_4/speed
uB_RackFans_TPC5_2_5/speed

#3 - 06/05/2015 07:53 AM - Glenn Horton-Smith

- Status changed from New to Resolved

- % Done changed from 0 to 100

Clarification: TPC5 has two fan packs in reality, had only one in the IOC db.

Added the second TPC5 fan pack to db and alarms

"Elizabeth" rack (ELIZ) has no fans in reality, had some in db

Removed all ELIZ fans from alarm and db.

#4 - 06/05/2015 10:12 PM - Glenn Horton-Smith

- Status changed from Resolved to Closed