

VME BPM - Bug #9345

Serial port not working on sbpmf1

07/01/2015 01:46 PM - John Diamond

Status:	Closed	Start date:	07/01/2015
Priority:	Normal	Due date:	
Assignee:	John Diamond	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.75 hour
Description			
Not receiving any serial connection from sbpmf1 on bootup. Had to replace with tstbpm3 so there is no node at TG9 right now. Will either need to fix sbpmf1 or replace tstbpm3 with another node.			

History

#1 - 07/01/2015 02:59 PM - John Diamond

- Status changed from New to Resolved

- % Done changed from 0 to 100

Found a MVME2434 'rrblt' in the cabinet upstairs.
Transferred the canbus card from sbpmf1.
Installed in crate at TG9 and configured as tstbpm3.fnal.gov.

#2 - 07/01/2015 03:17 PM - John Diamond

Submitted network device requests:
tstbpm3 -> sbpmf1
rrblt -> tstbpm3

#3 - 07/01/2015 03:26 PM - John Diamond

- Status changed from Resolved to Closed