

AD Main Injector Department - Issues by Age

#	Tracker	Status	Subject	Created
7754	Idea	Assigned	Rewrite application in Java	01/31/2015 10:15 PM
7935	Idea	New	Add RR 8 GeV line to program	02/24/2015 03:58 PM
8037	Bug	New	Booster > MI line trim calibration file needs to be updated	03/09/2015 07:46 AM
8297	Feature	New	RF parameters table	04/09/2015 11:52 PM
8298	Bug	New	Inconsistent behavior when setting anode program past "Max HV"	04/10/2015 12:25 AM
8303	Idea	New	Beam-Compensation current limit	04/11/2015 10:02 PM
8389	Bug	New	Tune setting should fail when any corrector reaches its current limit	04/21/2015 04:23 PM
8687	Feature	New	Increase data column count	05/08/2015 04:42 PM
11526	Idea	New	Remove momentum correction from program	01/28/2016 10:37 AM
11528	Bug	New	Need more accuracy for R50 desire file	01/28/2016 10:42 AM
11529	Bug	New	Abort button does not disappear	01/28/2016 10:51 AM
11818	Bug	New	H100 position comparison wildly wrong on compare	02/24/2016 02:54 PM
11819	Bug	New	Order newest files first	02/24/2016 02:56 PM
11820	Feature	Assigned	Add RR > P1 line closure	02/24/2016 02:59 PM
11823	Feature	New	Ability to close to a closure offset	02/24/2016 03:07 PM
11824	Feature	New	Ability to close on each injection	02/24/2016 03:09 PM
11837	Idea	New	Smoothing at profile timer 0 not as easy as it used to be	02/26/2016 03:14 PM
13053	Bug	Assigned	Remove ability to disable \$20/\$21 prepare for beam timer from program	06/27/2016 11:12 AM
14435	Bug	New	Trying to plot drfit sapce betas breaks plot feature	11/07/2016 04:13 PM
14436	Bug	Assigned	MI and RR_NOVA lattices very old	11/07/2016 04:16 PM
14742	Feature	Accepted	Setting dqH and dqV to zero should put 0 current on 30 quad trims	12/01/2016 03:03 PM
11821	Feature	New	New phase trombone	02/24/2016 03:06 PM
15030	Necessary Maintenance	Resolved	Need to switch to APVDB from APPDB	01/06/2017 11:02 AM
20643	Task	Assigned	Update Recycler Orbit Main Injector Ramp Compensation	08/20/2018 11:18 AM