

AD Main Injector Department - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
14436	Bug	Assigned	Urgent	MI and RR_NOVA lattices very old	Kyle Hazelwood	11/07/2016 04:17 PM
11528	Bug	New	High	Need more accuracy for R50 desire file	Kyle Hazelwood	01/28/2016 10:42 AM
8389	Bug	New	Normal	Tune setting should fail when any corrector reaches its current limit		04/21/2015 04:23 PM
8298	Bug	New	Normal	Inconsistent behavior when setting anode program past "Max HV"		04/10/2015 12:38 AM
8037	Bug	New	Normal	Booster > MI line trim calibration file needs to be updated		03/09/2015 07:46 AM
14435	Bug	New	Low	Trying to plot drfit sapce betas breaks plot feature		11/07/2016 04:13 PM
13053	Bug	Assigned	Low	Remove ability to disable \$20/\$21 prepare for beam timer from program	Kyle Hazelwood	06/27/2016 11:13 AM
11819	Bug	New	Low	Order newest files first		02/24/2016 02:56 PM
11818	Bug	New	Low	H100 position comparison wildly wrong on compare		02/24/2016 02:54 PM
11529	Bug	New	Low	Abort button does not dissappear	Kyle Hazelwood	01/28/2016 10:54 AM