

AD Main Injector Department

	2021-4				2021-5				2021-6				2021-7				2021-8				2021-9			
	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37
AD Main Injector Department																								
Main Injector and Recycler Beam Loss Monitor (...)																								
Need to switch to APVDB from APPDB	Resolved																							
Main Injector and Recycler Lattice Data Application (...)																								
Increase data column count	New																							
Trying to plot drfit sapce betas breaks (...)	New																							
MI and RR_NOVA lattices very old	Assigned																							
Main Injector Beam Line Smoothing Application (...)																								
Add RR 8 GeV line to program	New																							
Main Injector Orbit Smoothing Application (...)																								
H100 position comparison wildly wrong (...)	New																							
Order newest files first	New																							
Smoothing at profile timer 0 not as (...)	New																							
Remove ability to disable \$20/\$21 prepare (...)	Assigned																							
Main Injector Radiation Survey Application (...)	Main Injector Radiation Survey Application (PA4078, I128)																							
Rewrite application in Java	Assigned																							
Main Injector RF Control Application (PA1677, (...)																								
RF parameters table	New																							
Inconsistent behavior when setting anode (...)	New																							
Recycler Injecton Closure Application (PA4187, (...)	Recycler Injecton Closure Application (PA4187, R52)																							
Booster > MI line trim calibration file (...)	New																							
Add RR > P1 line closure	Assigned																							
Ability to close to a closure offset	New																							
Ability to close on each injection	New																							
Recycler Orbit Smoothing Application (PA4196, (...)																								
Remove momentum correction from program	New																							
Need more accuracy for R50 desire file	New																							
Abort button does not dissappear	New																							

Recycler Tune Control Application (PA4208, (...) Beam-Compensation current limit Tune setting should fail when any corrector (...) New phase trombone Setting dqH and dqV to zero shoud put (...) Studies Update Recycler Orbit Main Injector (...)	Recycler Tune Control Application (PA4208, R2) New New New Accepted Studies Assigned
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------