

Drivers - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
25026	Feature	Assigned	Normal	Add BBM support to MADC burst driver	Richard Neswold	09/29/2020 02:30 PM
16754	Feature	Closed	Normal	Driver needs to support alarms	Richard Neswold	11/21/2017 04:10 PM
11530	Feature	Assigned	Low	The V474 driver needs to support degaussing magnets	Richard Neswold	04/13/2018 03:10 PM
8126	Feature	Assigned	Normal	C1151 modules in beamline front-ends should support array devices.	Richard Neswold	05/03/2016 01:09 PM
8124	Feature	Assigned	Normal	Add a setting property to the beamline C154 to reflect the position setting	Richard Neswold	05/03/2016 01:11 PM