

## Main Injector RF Control Application (PA1677, I3) - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
8298	Bug	New	Normal	Inconsistent behavior when setting anode program past "Max HV"		04/10/2015 12:38 AM
7639	Bug	Closed	High	Saving file doesn't work	Kyle Hazelwood	01/31/2015 03:59 AM